



Train #	216	Car #	TC1	<del>TC1</del>	M1	M2	M3	M4	TC2	Process Stage	PC02	Inspector	Munich Richmond	Date	08/03/24	Page	____ of ____
Item	Defect Code	Demerit Class	Description of Defects								Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off	
1			Paint chips on end UF								UF	2	R	Supplier	<del>Richmond</del>	<del>Richmond</del>	
			Splatters on LV brackets								UF	1&2	L&R	CB1150	<del>Richmond</del>	<del>Richmond</del>	
			White stains on Lower guide rail								UF	1&2	L&R	FT1042 1041	<del>Richmond</del>	<del>Richmond</del>	
GIBELQ		GIB0000000380	Rev A0		Defects Report								29/03/2017 4/5 Pages				



Train #	216	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page		
Item	Defect Code	Demerit Class	Description of Defects						Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work Instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
1			Rust on EWF on Mastix.							1	R			
2			Spatters on Tapping pads area							2	L/R			
3			General paint touch ups on ULF - from buffer etc * Uburge							1/2	L/R			
4			Sealant gap on ULF panel						1150	2	L			
5			Paint dripping End 2							2	L/R			
														
														

[illegible]



