





[illegible]

| Train #   | Car #       | TC1           | M1                          | M2 | M3 | M4 | TC2 | Process Stage | RCO2 | Inspector                     | End | Side | Action Required   | Quality Sign-off | Prasa Sign-off |
|---|-------------|---------------|-----------------------------|----|----|----|-----|---------------|------|-------------------------------|-----|------|---|------------------|----------------|
| DS  | M4          |               |                             |    |    |    |     |               |      |                               |     |      |   |                  |                |
| Item  | Defect Code | Dementi Class | Description of Defects      |    |    |    |     |               |      | Localisation                  | End | Side | Action Required   | Quality Sign-off | Prasa Sign-off |
| 1   |             |               | Part change on Fuel 2 Crash |    |    |    |     |               |      | Interior underframe, roof etc | 2   | L    | (Ready to fix/part needed /MCR/ Work instruction required for special process rework) |                  |                |
|    |             |               |                             |    |    |    |     |               |      |                               |     |      |   |                  |                |
|   |             |               |                             |    |    |    |     |               |      |                               |     |      |   |                  |                |
|    |             |               |                             |    |    |    |     |               |      |                               |     |      |   |                  |                |

GIBELG

GIB0000000380

Rev A0

Defects Report

29/03/2017

4/5 Pages

[illegible]

[illegible]

| Train #   | Car #        | TC1                          | M1 | M2 | M3 | M4 | TC2 | Process Stage   | Inspector                        | Date   | Page  |                  |                |
|-----------|--------------|------------------------------|----|----|----|----|-----|---|----------------------------------|--|---|------------------|----------------|
| 225       | M3           |                              |    |    |    |    |     |   |                                  | 14/05/24                                     | 4/5   |                  |                |
| Item Code | Defect Class | Description of Defects       |    |    |    |    |     | Localisation<br><small>Interior, underframe, roof etc</small> | End<br><small>[1] or [2]</small> | Side<br><small>Left [L] or Right [R]</small> | Action Required<br><small>(Ready to fix/Part needed/ NCR/ Work instruction required for special process remark)</small> | Quality Sign-off | Prasa Sign-off |
|           |              | generic part under crash box |    |    |    |    |     | 34F   | 1                                |  |   |                  |                |
|           |              |                              |    |    |    |    |     |   |                                  |  |   |                  |                |

GIB000000380




Rev A0

Defects Report

29/03/2017

4/5 Pages

This document and the information contained herein have to be considered as Confidential Information pursuant to the provisions of Clause 22 of the MCA and treated as such.

| Train #   |              | Car #                  | TC1 | M1 | M2 | M3 | M4 | TC2 | Process Stage                   | Inspector  | Date                  | Page   |          |          |
|---|--------------|------------------------|-----|----|----|----|----|-----|---------------------------------|------------|-----------------------|--|----------|----------|
| 225   |              | TC2                    |     |    |    |    |    |     |                                 | Benj       | 14/05/2017            | 4/5  |          |          |
| Item Code   | Defect Class | Description of Defects |     |    |    |    |    |     | Localisation                    | End        | Side                  | Action Required  | Quality  | Prasa    |
|   |              |                        |     |    |    |    |    |     | Interior, underframe, roof etc. | [1] or [2] | Left [L] or Right [R] | (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework.) | Sign-off | Sign-off |
| No issues   |              |                        |     |    |    |    |    |     |                                 |            |                       |  |          |          |
|   |              |                        |     |    |    |    |    |     |                                 |            |                       |  |          |          |
|  |              |                        |     |    |    |    |    |     |                                 |            |                       |  |          |          |
|  |              |                        |     |    |    |    |    |     |                                 |            |                       |  |          |          |

GIBBELD

GIBD000000380

Rev A0

Defects Report

29/03/2017

4/5 Pages