


[illegible]

Train #	227	Car #	M2	TC1	M1	M3	M4	TC2	Process Stage	PC02	Inspector	Amo + Magadi	Date	20/05/24	Page	4/5
Item	Defect Code	Demerit Class	Description of Defects							Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off	
1		C	General spatters on EUFI (CB1216)								1+2	L+R				
2		C	Rust on side sill ring welds (CB1156) - General								1+2	L+R				
3		C	Two toned paint on EUFI (CB1070) - General								1+2	L+R				
		C	Paint touch up on EUFI next to UF bracket								1	R				
																

This document and the information contained herein have to be considered as Confidential Information pursuant to the provisions of Clause 25 of the M&A, and treated as such



GIB0000000380

Rev A0

Defects Report

29/03/2017

4/5 Pages

