

[illegible]

[illegible]

[illegible]

[illegible]



Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	NTL / Snelby	Date	Page		
229	M3										30/05/24	4		
Item	Defect Code	Demerit Class	Description of Defects						Localisation Interior, underframe, roof etc	End (1) or (2)	Side Left (L) or Right (R)	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
1			Paint touch ups on tapping rods - U1F						(1150)	1+2	L+R			
2			Spatters on U1F (1150)											
3			Rust on Euf 1							1	L+R			

[illegible]