

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page			
730	TC1								NTL	3/05/24	4/5			
Item	Defect Code	Demerit Class	Description of Defects						Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Pass Sign-off
1			Sealant gap						1041					
<div style="display: flex; justify-content: space-between;"> <div> </div> <div> GIB0000000380 <div>Rev A0</div> </div> <div> Defects Report <div>29/03/2017</div> </div> </div>														

[illegible]

[illegible]

Item	Defect Code	Demerit Class	Description of Defects	Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
1		C	Insufficient paint applied on EUF spacewelds (CB1230)		2	R	R.T.F		
2		C	Bye pen residue on EUF (CB1150)		2	R	R.T.F		
3		C	Paint drip marks on UE bracket (CB1150)		1	R	R.T.F		

This document and the information contemplated therein have to be considered as Confidential Information pursuant to the provisions of Clause 25 of the MSA, and treated as such

[illegible]

This document and the information contemplated therein have to be considered as Confidential Information pursuant to the provisions of Clause 25 of the MSA, and treated as such