



Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page	OF						
246	TC1								NT/Key/Syd	18/05/24								
Item	Defect Code	Demerit Class	Description of Defects						Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework.)	Quality Sign-off	Prasa Sign-off				
			Cracking Sealant on 4th panel							1	L							
																		
																		

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page			
ML	ML								Kulley ML	15/05/14	4/5			
Item	Defect Code	Demerit Class	Description of Defects						Localisation Interior, underframe, roof etc	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
1			Spatter residue on Side sill						1150	1	R			
2			Paint damage on VLF bracket						1150	1	L			

[illegible]

[illegible]