


Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page			
231	M2									10/05/20	4/5			
Item	Defect Code	Dement Class	Description of Defects						Localisation	End	Side	Action Required	Quality	Prasa
			Including spiders on end window frame panels						LF	2	2	CR1070		
			Touch up paint required on end window frame (internal) lighting panel						LF	2	2	CR1070		
			Scraper visible on end window frame end basic area						LF	1	R	CR1070		

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Mu. Lead	Date	To/From	Page	
231	M3												4 of 4	
Item	Defect Code	Demerit Class	Description of Defects						Localisation	End	Side	Action Required	Quality	Prasa
									Interior, underframe, roof etc.	[1] or [2]	Left [L] or Right [R]	(Ready to fix/Part needed/ NCV/ Work instruction required for special process rework)	Sign-off	Sign-off
			Bidding spacers on underframe panels						LIF	1st	Left	C1070		
			Former visible on end 2 and UF						UF	2	Left	C1070		
			Paint touch-ups / scratches due to lifting						UF	1st	Left			
			Detaching sealant on UF panels						UF	2nd	Left	C1070		
			End underframe scratched on end 1						LIF					
			Lifts near junction box											
														

Train #	231	Car #	TC2	TC1	M1	M2	M3	M4	TC2	Process Stage	PC02	Inspector	NEG + AMO	Date	11/06/24	Page	OF																		
Item	Defect Code	Demreit Class	Description of Defects										Localisation Interior, underframe, roof etc.	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NOCV/Work Instruction required for special process rework)	Quality Sign-off	Prasa Sign-off																	
DECLARATION: END 2 IC BOXES																																			

GIB0000000380

Rev A0

Defects Report

29/03/2017

4/5 Pages

This document and the information contained therein shall be considered as Confidential Information pursuant to the provisions of Clause 25 of the AGA, and treated as such

[illegible]

Train #	231	Car #	TC1	<input checked="" type="checkbox"/> M1	M2	M3	M4	TC2	Process Stage	Inspector	Neo + Amc	Date	10/06/27	Page	of
Item	Defect Code	Dement Class	Description of Defects						Localisation	End	Side	Action Required	Quality	Prasa	
									Interior, underframe, roof etc	[1] or [2]	Left [L] or Right [R]	(Ready to fix/Part needed/ NCR/ Work instruction required for special process rework.)	Sign-off	Sign-off	
			NO ISSUES												

This document and the information contained herein shall be considered as Confidential Information pursuant to the provisions of Clause 23 of the M&A and treated as such