

[illegible]

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page			
211	M4								NTL	16/02/24	4/5			
Item Code	Defect Class	Description of Defects							Localisation Interior, underframe, roof etc	End (1) or (2)	Side Left (L) or Right (R)	Action Required (Ready to fit/Part needed/ NCR/ Work instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
1		Sealant Cracked on A/F panel								2	L/R	RTF		

[illegible]

[illegible]

[illegible]