

[illegible]

[illegible]

[illegible]

[illegible]

Train #	233	Car #	M3	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Nik/Ludwig	Date	24/06/21	Page	4/5
Item	Defect Code	Dementit Class	Description of Defects							Localisation	End	Side	Action Required	Quality	Prasa	
										Interior, underframe, roof etc.	[1] or [2]	Left [L] or Right [R]	(Ready to Ex/Part needed NCR/ Work Instruction required for special process rework)	Sign-off	Sign-off	
			Mastic not applied on End 2								2					
			Pore on Sealant Euf 1 LHS													
<div style="display: flex; justify-content: space-between;"> GIB0000000380 Rev A0 Defects Report </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> 29/03/2017 4/5 Pages </div>																

This document and the information contained therein are to be considered as confidential information pursuant to the provisions of Clause 23 of the PCC, and treated as such.

[illegible]